

400 Seventh St. S.W. Washington, D.C. 20590

2006 Natural Gas Program Evaluation Document for Washington Utilities and Transportation Commission

Document Legend:

PART:

O -- Representative Date and Title Information

A -- General Program Compliance

B -- Inspections(Procedures, Records, forms)

C -- LNG Inspections

D(1) -- Compliance 60105(a) States
D(2) -- Compliance 60106(a) States
D(3) -- Compliance-Interstate Agents
E -- Incident Investigations

E -- Incident InvestigationsF -- Field Inspection



2006 Natural Gas Program Evaluation Document -- CY 2006 (Natural Gas)

State Agency: Washington

Rating:

Agency Status:

60105(a): Yes 60106(a): No Interstate Agent: YES

julikojomak esta ligilikota kiusu likutojomakojikomiki

Agency Representative: Dave Lykken

Date of Visit: 8/13/2007-8/17/2007

OPS Representative: Tom Finch and Rex Evans

Commission Chairman to whom follow up letter is to be sent:

Name/Title:

Mr. Mark Sidran, Chairman

Agency:

Washington Utilities and Transportation Commission

Address: City/State/Zip:

1300 Evergreen Park Drive SW Olympia, Washington, 98502

INSTRUCTIONS:

Complete this evaluation in accordance with the Procedures for Evaluating State Pipeline Safety Program. The evaluation should generally reflect state program performance during CY 2006 (not the status of performance at the time of the evaluation). All items for which criteria have not been established should be answered based on the OPS representative's judgment. A deficiency in any one part of a multiple part question should be scored as needs improvement. Circle the correct answer; then place the score in the points column. If a state receives less then the maximum points, include a brief explanation in the space provided for general comments/regional observations. If a question is not applicable to a state, delete the question and deduct the points from the total possible points. Please ensure all responses are COMPLETE and ACCURATE, and OBJECTIVELY reflect state program performace. Increasing emphasis is being placed on performance. This evaluation together with selected factors reported in the state's annual certification/agreement attachments provide the basis for determining the state's pipeline safety grant allocation.

Field Inspection PART F

The field inspection form used will allow different areas of emphasis to be considered for each question. Questions 6,7 and 8 are provided for scoring this portion of the field inspection. In completing PART F, the OPS representative should include a <u>written summary</u> which thoroughly documents the inspection.



PART A -General Program Compliance	Points(MAX)	Score
A. 1 Yes = 8 No = 0 Needs Minor improvement = 3-7 Needs Major Improvement = 2 Did the state submit complete and accurate information on the attachments to its most current 60105(a	8	7
Certification /60106 (a) Agreement? (NOTE: OPS Representative to verify certification/agreement attachments by reviewing appropriate state documentation. Score a deficiency in any one area as "needs improvement". Attachment numbers appear in parentheses.)		
a. State Jurisdiction and agent status over gas facilities(1)	X	
U. Folar state inspection activity(2)	lył	
c.Gas facilities subject to state safety jurisdiction(3)	X	
d. Cas pipeline incidents(4)	ixi	
e. State compliance actions(5)	1 1	
1. State record maintenance and reporting(6)	(V)	
g.State employees directly involved in the gas pipeline safety program(7) h.State compliance with Federal requirements(8)	IXI	
SLR NOTES:		
Attachment I and 3 they had 17 master meter operators listed but forgot to add the 2 new master meter operators ass soon as possible.	ors on Attachment 3.	They will
e. State Compliance Actions had 35 but should have 56 on intrastate and had 18 but should have been 20 carri	ed over.	
A.2 Yes = 1 No = 0 Did the state have an adequate mechanism to track operator reporting of incidents to ensure state compliance with 60105(a) Certification/60106(a) Agreement requirements (fatality, injury requiring hospitalization, property damage exceeding \$50,000)?	1	1
LR NOTES: Yes		
A.3 Yes=3 No=0 Needs Improvement = 1 Did the state take appropriate follows up actions related to the appropriate incident and the		<u>1 1.8</u>
A.3 Did the state take appropriate follow-up actions related to the operator incident reports? LR NOTES:	3	3
Yes on both of their incidents in 2006.		
A.4 Yes = 5 No = 0 Has the state held TSI seminar(s) in the last 3 years? (NOTE: Indicate date of last seminar or if state requested seminar, but TSI could not provide, indicate date of state request for seminar)	. 5	. 5
LR'NOTES: Yes on 10/25/05 in SeaTac/Seattle, WA.		
A.5 Yes = 2. No = 0 Needs Impovement = 1 Were pipeline safety program files well-organized and kept in a secure, readily accessible location?		
LR NOTES:	2	2
Yes	•	
A.6 Yes = 5 No = 0 Needs Innovement = 3 Did state records and discussions with the state pipeline safety program manager indicate adequate knowledge of OPS program and regulations?	. 5	5
R NOTES:		200
Yes with Dave Lykken. We suggest that the actual pipeline safety program manager as the program manager s annual evaluation so that we can evaluate him to verify that he has adequate knowledge of our program and reg	pend more time during ulations.	ş our
A.7 Yes = 5 No = 0 Needs Impovement = 3 Did the state encourage and promote programs to prevent damage to pipeline facilities as a consequence of demolition, excavation, tunneling, or construction activity?		5 .
R NOTES:	region artist. Transport	San San San San San San
Yes the same as the liquids. Investigating contract locate companies. Should go after the operator who has the They are responsible for enforcing Part 192. Sweeney attends LEPC meetings.	the ultimate responsa	bility.
A.8 Yes = 0 No = 0 Have there been modifications or proposed changes to inspector staffing levisle? If yes describe	0	0
R NOTES:		i i i ka ka t
The same as the liquids.	and the second s	(1) (1) (1) (1) (1)
A.9 Yes=0 No=0 What were the major accomplishments for the year being evaluated? Describe the accomplishments. (Information Question)	0	0
(intornation Question)		5- 6197 1112
	SEATS SE	
R NOTES: 1. Small Gas Pipeline Study:	alente es	

Background:

There are other small gas systems that do not meet the federal master meter definition yet potentially pose a safety hazard. Gas pipeline systems that are publicly-owned or distribute propane gas are currently not inspected or regulated in the same manner as master meter systems. This study is intended to gather information about all small gas pipeline systems with the intention of determining whether any changes are necessary to the state's safety oversight program. This inquiry may inform a future rulemaking and could guide the commission in a request for changes in state law.

2. Public Awareness:

Assisted operators in complying with the new PA rule. Tim Sweeney our Public Outreach Coordinator attended several meetings to brief operators on the requirements of the PA rule.

- 3. Web Access to pipeline maps (pilot program)
- 4. Web access to standard and specialized inspection reports
- 5. One-call enforcement emphases

Seek enforcement against excavators who habitually dig before calling for locates.

Currently conducting investigation regarding Third Party locating service not meeting requirement to complete locate requests 2 days prior to scheduled excavation.

A. 10 Yes=0 No=0 What legislative or program initiatives are taking place/planned in the state, past, present, and future?

Describe initiatives (i.e. damage prevention, jurisdiction/authority, compliance/administrative, etc.) (Information Question)

0

SLR NOTES:

1. Senate Bill 5225 became law on July 22, 2007, the first major revision to Washington's pipeline safety act since 2001. The legislation consolidates all pipeline safety authority under one chapter of law. It clarifies the UTC's authority over pipeline safety and updates state statutes to conform to federal pipeline-safety requirements. The House and Senate passed the bill without any no votes.

In 2007 the UTC will begin rulemaking to conform its rules to the major provisions of the new law:

- . Increase maximum penalties for pipeline-safety violations so they are consistent with federal law. The state maximum penalty will increase to \$100,000 for each violation a day from its current \$25,000 level. The penalty change applies to hazardous liquid and gas pipelines operating within the state.
- . Define "gas" so that it will extend state pipeline-safety regulation to include hydrogen and acid-gas pipelines.
- . Extend state pipeline-safety regulation over publicly owned small pipeline systems called "master meters," that are currently subject to federal pipeline safety rules. An example of a publicly owned master meter system is one owned by a public housing authority where the tenant either pays the agency directly or indirectly for the gas received.
- . Allow for state pipeline-safety regulation over propane pipeline-distribution systems regardless of whether propane rates are regulated by the commission.
- 2. Refer to items under Question A10 (Major Accomplishment) for Program Initiatives
- 3. Training opportunities exceed requirements found in State program requirements
- A. 11 Yes of no response required = 5 No = 0

 Did the state respond in writing within 45 days to the requested items in the Chairman's letter following the Region's last program evaluation? (Region representative may allow 15 additional days for documented circumstances)

ja.

SLR NOTES:

Yes they responed on March 16th to our January 31st letter.

A. 12 Yes=5 No=0

Has each inspector fulfilled the 3 year TSI training requirement? If No, has the state been granted a waiver regarding TSI courses by the Associate Administrator for Pipeline Safety? (NOTE: If the State has new inspectors who have not attended all TSI courses, but are in a program which will achieve the completion of all applicable courses within 3 years of employment, or if a waiver has been granted by the Associate Administrator for Pipeline Safety, please answer yes.)

SLR NOTES:

Lex Vinsel is due to complete his by August of 2009. Also recommend that you switch Al Jones out and their new inspector Stephanie Z, in for the PL00250 class early in 2008.

A.13 Brief Description of Non-TSI training Activities
For State Personnel:

For State Personnel

NTSB Courses:

Human Fatigue Factors
Al Jones
Joe Subsits
Kuang Chu

Patti Johnson Scott Rukke Cognitive Interviewing Techniques Joe Subsits Kuang Chu Patti Johnson Scott Rukke Clarion Course: Integrity Management Programs Joe Subsits For Operators: For Non-Operator Entities/Parties, Information Dissemination, Public Meetings: SLR NOTES: Brief Description of Non-TSI Training Activities For State Personnel NTSB Courses: **Human Fatigue Factors** Al Jones Joe Subsits Kuang Chu Patti Johnson Scott Rukke Cognitive Interviewing Techniques Al Jones Joe Subsits Kuang Chu Patti Johnson Scott Rukke Clarion Course: Integrity Management Programs Joe Subsits A.14 Part-A General comments/Regional Observations/Computer Inventory A SLR NOTES: Same as for liquids. Their Pipeline Safety Program Manager needs to participate more in our annual evaluations and as other Pipeline Safety Program Managers do be there for the complete evaluation. Computer Inventory: Quantity Description Year Make Model Serial Number Federal Dell Processor TSC#98823 Speakers
Speakers
Samsung Flat Screen Monitor
HP PSC 2410 (All in one printer)
HP Scanjet Scanner 4600
HP Scanjet Scanner 1 set Samsung MY19HCHX505286 MY41SI36JF HP CN3BMB7638 TSC#92227 A.15 What actions did the State initiate as a result of issues raised in the Chairperson's letter from the previous year? Did actions correct or address deficiencies from previous year's evaluation? SLR NOTES: Yes they addressed our three major items and had no major deficiences in 2005 to correct. 6 Yes=1 No=0
Did the lead inspectors complete all required TSI OQ courses and Computer based training before conduction IMP inspection? A.16 SLR NOTES: Yes the lead inspectors did complete all required TSI OQ couses and Computer based training before conduting OQ inspections. A.17Did the lead inspectors complete all required IMP Courses/Seminars and CBT before conducting IMP inspection? SLR NOTES: Yes the lead inspectors completed all required IMP Courses/Seminars and CBTs before conducting IMP inspections.

A. 18 What is the state doing at present concerning the "Common Ground Study" and Damage Prevention?

0

SLR NOTES:

Nothing on CGA. Tim Sweeney doing outreach and attending local LEPC meetings and the WUTC is taking action against operators, excavators and third party locating contractors that violate their damage prevention laws.

. The common was sufficient to the special property of the control of the control

Total points scored for this section: 41

Total possible points for this section: 42

李老子等 物語

Did the state adequately review operator procedures for surveillance of cast iron pipelines, including appropriate action resulting from tracking circumferential cracking failures, study of leakage history, or other unusual operating maintenance condition? (Note: If state accepts guidelines less stringent that the AGA GPTC Appendix G-18, circle needs improvement)

SLR NOTES:

Yes

Yes = 2 No = 0 Needs Improvement = 1 B.9 Did the state review operator emergency response procedures for leaks caused by excavation damage near buildings and determine whether the procedures adequately address the possibility of multiple leaks and underground migration of gas into nearby buildings Refer to 4/12/01 letter from OPS in response to NTSB recommendation P-00-20 and P-00-21?

SLR NOTES:

Yes their inspection of Cardinal FG is an example,

Did the state review records of previous accident investigations including reported third party damage and leak response to ensure appropriate operator response as required by Part 192.617?

SLR NOTES:

Yes it is in the procedures checklist 192.617 and should be in the records checklist.

B.11 Yes = 2 No = 0 Needs Improvement = 1 Has the state reviewed underground directional drilling/boring procedures of each operator and their contractors to determine if they include effective actions to protect their underground facilities from the dangers posed by directional drilling and other trenchless technologies? These procedures should include, but are not limited to, accurately locating underground piping and reviewing the qualifictions of personnel performing the work.	2	2
SLR NOTES:		
Yes per the Advisory Bulletin it should be on the inspection checklist. Dave will remind his inspectors to ask the	his.	
B.12 Yes = 5 No = 0 Was the ratio acceptable of Total inspection Person-days to Total Person-days charged to the program by state inspectors? (Regional director may adjust points for just cause.) A.Total Inspection Person Days (Attachment 2)=	5	5
B.Total Inspection Person Days Charged to the program(220 X Number of Inspection person years(Attachment	7)=0	•
Formula: $-Score = A/B = /0 = 0$,
Rule: (If score \geq 38 then points = 5 else Points = 0.) Thus Points = 0		
SLR NOTES:	1	
= 571.9/5.33x220=571.9/1272.6=0.45 =Yes		
D 12 Yes = 3 No = 0 Needs Improvement = 1	<u></u>	
Did the state adequately document sufficient information for probable violations?	3	3
SLR NOTES:		
Yes concerning the Weyerhauser and Cardinal FG violations.		
B.14 Part-B General Comments/Regional Observations	0	
B.15 Did the State input all operator qualification inspection results into web based database provided by PHMSA in a timely manner upon completion of OQ inspections?	0	
SLR NOTES:		•
Yes per my recent check of the OQ database with our John Haddow.		
B.16 Did the State submit their replies into lintegrity Management Database (IMDB) in response to the Operators notifications for their integrity management program?	0	
SLR NOTES:		•
Yes per my check of the Gas IMP database with our Peter Katchmar.	•	
B.17 Has the Federal Protocol form been uploaded to the Integrity Management Database (IMDB)?	0	
SLR NOTES: Yes it has for the WUTC. I need to email Buddy Sheets about the bp liquid OandM review.		
B.18 Did the State ask Operators to identify any plastic pipe that has shown a record of defects/leaks and what those operators are doing to mitigate the safety concerns?	0	
LR NOTES:		
Yes they ask that per their checklist. PSE - working toward putting them in a replacement program. Total points scored for		34
Total possible points fo	N miż Séction:	36

PART C -LNG Inspections	Points(MAX)	Score
C. 1 Yes = 2 No = 0 Did the state inspect LNG facilities in accordance with time intervals in its written procedures? Frequency of LNG inspections: (Please Specify time frame in the Note)	2	NA
SLR NOTES: Yes they did and do them annualy. Williams Gas and PSE.		
C.2 Yes = 1 No = 0 Did the state fill out inspection form(s) or checklist(s) covering the design, construction, operation, an maintenance of LNG facilities in sufficient detail?	d 1	1
SLR NOTES: Yes on the interstate.		
C.3 Yes = 3 No = 0 Needs Improvement = 1 Do inspection records sufficiently document review of OandM plans, Emergency plans, personnel qualification, and training?	3	3
SLR NOTES: Yes on the interstate inspection.		
C.4 Yes = 2 No = 0 Do the inspection records adequately document the discovery and nature of probable violations?	2	2
SLR NOTES: Yes		
C.5 Yes = 1 No = 0 Part C: General Comments/Regional Observations	1	NA
LR NOTES: Why is there a point assigned to General Comments/Regional Observations.		
	2 X) No () Needs Impro	2 evement
b.History of Operator/Unit and/or location(including leakage,incident, and compliance history) Yes (X) No O Needs Impro	vement 💍
LR NOTES: They do the 1 interstate and one intrastate inspection annualy.		
C.7 Yes = 3 No = 0 Needs Improvement = 1 or 2 Does the state utilize Federal Inspection forms? If the state utilized alternative inspection forms, did the inspection forms cover all code requirements addressed on federal inspection forms?	3	3
LR NOTES:		
Yes on the interstate and the intrastate forms.		
Total points scored Total possible point		11 11

PARTD(1) - Compliance 60105(a) States	Points(MAX)	Score
D(1). 1 Yes = 2 No=0 Needs Improvement = 1 Does the state have written procedures or a mechanism identifying the steps to be taken from the discovery to the resolution of a probable violation as specified in the "Guidelines for States Participating in the Pipeline Safety Program", Chapter 5?	. 2	2
SLR NOTES: Yes the same as the liquids.		
D(1).2 Yes=2 No=0 Needs Improvement = 1 Does the state have written procedures or a mechanism for notifying an operator when a noncompliance is identified as specified in the "Guidelines for States Participating in the Pipeline Safety Program", Chapter 5?	e 2	2
SLR NOTES: Yes the same as the liquids.	• .	
D(1).3 Yes = 2 No = 0 Needs Improvement = 1 Does the state have a written procedure or mechanism for routinely reviewing the progress of compliance actions to prevent delays or breakdowns of the enforcement process, as required by the "Guidelines for States Participating in the Pipeline Safety Program", Chapter 5?	2	2
SLR NOTES: Yes the same as the liquids. They do need to look more at carryovers from year to year on attachment 5.	•	
D(1).4 Yes = 4 No = 0 Needs Improvement = 1-3 Did the State issue any compliance actions in the last 3 years ?(Note: PHMSA representative has discretion to delete question or adjust points, as appropriate, based on number of probable violations; any change requires written explanation)	4	4
SLR NOTES:		
Yes they did issue compliance actions in the last 3 years, i.e., Weyerhauser and many others.		
D(1).5 Yes = 2 No = 0 Needs Improvement = 1 Did the state follow its written procedures or a mechanism in Question 4 for reviewing compliance actions and follow-up to determine that prompt corrective actions were taken by operators, within the time frames established by the procedures and compliance correspondence, as required by the ?Guidelines for States Participating in the Pipeline Safety Program?, Chapter 5? LR NOTES:	2	2
Yes the same as the liquids.		
D(1).6 Yes = 0 No = 0 If compliance could not be established by other means, did state pipeline safety program staff request formal action, such as a "Show Cause Hearing" to correct pipeline safety violations? (Information Question)	Ó	NA
LR NOTES:		
NA not yet but they may have one with PSE in 2007.	•	•
D(1).7 Yes = 2 No = 0 Needs Improvement = 1 Did the state adequately document the resolution of probable violations?	2	2
R NOTES:		
Yes they did with all the inspection folders that we looked at.		
D(1).8 Yes = 1 No = 0 Were compliance actions sent to a company officer (manager or board member if municipal/government system)?	1	1
R NOTES:		2
Yes to The VP and Mill Manager of Weyerhauser for example. They do send to the Manager for Regulatory C was to the Senior Director of Engineering and should be sent to a Company Officer with a copy to the Senior D	ompliance. Cascade N irector.	latural Gas
D(1).9 Yes = 2 No = 0 Needs Improvement = 1 Did the compliance proceedings give reasonable due process to all parties?	2	. 2
R NOTES: Yes the same as the liquids.		1, 1
O(1).10 Part D(1): General Comments/Regional Observations	0	
Total points scored f Total possible points	and the second s	17 17

PARTD(2) - Compliance 60106(a) States		Score
D(2). 1 Yes = 2 No = 0 Needs Improvement = 1 Did the state use an inspection form, approved by the Regional Director, covering applicable regulations in sufficient detail?	2	NA
D(2).2 Yes = 2 No = 0 Needs Improvement = 1 Are results adequately documented demonstrating inspection units were reviewed in accordance with state inspection plan?	2	NA
D(2).3 Yes=5 No=0 Needs Improvement = 2 Were any cases referred to OPS for compliance in the last 3 years? (NOTE: OPS representative has discretion to delete question or adjust points, as appropriate, based on number of probable violations; any change requires written explanation.)	5	NA
D(2).4 Yes=2 No=0 Needs Improvement = 1 Did the state immediately report to OPS conditions which may pose an imminent safety hazard to the public or to the environment?	2	NA
D(2).5 Yes = 2 No = 0 Needs Improvement = 1 Did the state give written notice to OPS within 45 days of all probable violations found?	2	NA
D(2).6 Yes = 5 No = 0 Needs Improvement = 2 Did the state initially submit adequate documentation, on report format approved by Regional Director to support compliance action by OPS on probable violations?	, 5	NA
D(2).7 Part D(2): General Comments/Regional Observations	0	

PARTD(3) - Compliance-Interstate Agents	Points(MAX)	Score
D(3).1 Yes = 2 No = 0 Needs Improvement = 1 Did the state use an inspection form, approved by the Regional Director, covering applicable regulations in sufficient detail in accordance with the interstate agent agreement?	2	2
SLR NOTES: Yes		
D(3).2 Yes = 2 No = 0 Needs Improvement = 1 Are results adequately documented demonstrating inspection units were reviewed in accordance with directed inspection plan"?	2	2
SLR NOTES: Yes per our Interstate AgentInspection Work Plan.		
D(3).3 Yes = 2 No = 0 Needs Improvement = 1 Did the state submit documentation of the inspections within 45 days as stated in its latest Interstate Agent Agreement form?	2	2
SLR NOTES: Yes they did even after waiting on the documentation from an operator.		
D(3).4 Yes = 5 No = 0 Needs Improvement = 2 Were any cases referred to OPS for compliance in the last 3 years? (NOTE: OPS representative has discretion to delete question or adjust points, as appropriate, based on number of probable violations; any change requires written explanation.)	5	5
LR NOTES: Yes in many cases.	•	
D(3).5 Yes = 2 No = 0 Needs Improvement = 1 Did the state immediately report to OPS conditions which may pose an imminent safety hazard to the public or to the environment?	2	2
LR NOTES: Yes especially the Spokane Williams release.		٠
D(3).6 Yes = 2 No = 0 Needs Improvement = 1 Did the state give written notice to OPS within 45 days of all probable violations found?	2	2
LR NOTES: Yes they did.		
D(3).7 Yes = 5 No = 0 Needs Improvement = 2 Did the state initially submit adequate documentation, on report format approved by Regional Director, to support compliance action by OPS on probable violations?	5	· 5
LR NOTES: Yes		•
D(3).8 Part D(3): General Comments/Regional Observations	0	.*
JR NOTES: The WUTC does a good job as an Interstate Agent.		
Total points scored Total possible point		20 20

PART E -Incident Investigations	Points(MAX)	Score
E. 1 Yes = 2 No = 0 Needs Improvement = 1 Are state personnel following the procedures for Federal/State cooperation in case of an incident (Appendix C in "Guidelines for States Participating in the Pipeline Safety Program")? SLR NOTES:	2	2
Of the 2 incidents one was rock impingement, and the other was a bad weld so no no violations.		
E.2 Yes = 2 No = 0 Needs Improvement = 1 Are state personnel familiar with the jurisdictional authority and Memorandum of Understanding (Appendix B in "Guidelines for States Participating in the Pipeline Safety Program") between NTSB and OPS?	2	2
SLR NOTES: Yes I asked Kuang Chu and he answered correctly.		•
E.3 Yes = 2 No = 0 Needs Improvement = 1 Did the state keep adequate records of incident notifications received?	2	2
SLR NOTES: Yes for Williams Gas's 2 incidents.		
E.4 Yes = 2 No = 0 Needs Improvement = 1 If an onsite investigation of an incident was not made, did the state obtain sufficient information by other means to determine the facts and support the decision not to go on-site?	2	NA .
SLR NOTES: NA both incidents were investigated.		
E.5 Yes = 5 No = 0 Needs Improvement = 2 Were investigations thorough and conclusions and recommendations documented in an acceptable manner? a. Observations Yes	5 ②N-	5
b. Contributing factors Yes c. Recommendations to prevent recurrences where appropriate Yes	(X) No () Needs Impro	ovement (
LR NOTES: Yes	(X) No () Needs imple	yemen (
E.6 Yes = 3 No = 0 Needs Improvement = 1 Did the state follow-up on any violations found during an incident investigation?		
LR NOTES: NA no violations.	3	NA
E.7 Part E: General Comments/Regional Observations	0	
LR NOTES: Do a good job working with PHMSA concerning incidents.		
E.8 Yes = 0 No = 0 Needs Improvement = 0 Did the state take appropriate follow-up actions related to Operator incident reports?	0	0
LR NOTES: Yes they followed up in an acceptable manner.		
E.9 Yes = 0 No = 0 Needs Improvement = 0 Did the state work with PHMSA to ensure that incident/accident reports are accurate and updated?	0	0
R NOTES: Yes, Total points scored	in in the second se	1. 1. 2. 1. 1. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2.
Total possible point		11.

	•	
PART F -Field Inspection	Points(MAX)	Score
F.1 Operator Inspector I continue Date OBS Beautiful Information		
Operator, Inspector, Location, Date, OPS Representative Information Name of Operator Inspected:	0	
BP Pipelines (North America), Inc.	•	
Name of State Inspector(s) Observed:	•	
Joe Subsits		
Location of Inspection:		
Ferndale, WA		
Date of Inspection: August 27 - 31, 2007		
Name of Operator Inspected:	•	
Jerry Kenerson		
SLR NOTES:		
The Ferndale (gas) pipeline systems was inspected.		
	·	
F.2 Yes=2 No=0 Did the inspector use an acceptable inspection form/checklist?	2	2
SLR NOTES:		_
The inspector used the Standard Inspection Checklist (with WUTC supplemental requirements), 2007 Edition		
		
F.3 Yes = 2 No = 0 Did the inspector thoroughly document results of the inspection?	2	Ż
SLR NOTES:		
Thorough documentation was completed by the inspector.		
F.4 Yes = 1 No = 0 Is the inspector using the inspection form/checklist as a guide for the inspection?	1	. 1
LR NOTES:		
The inspector used the inspection checklist as a guide throughout the entire inspection process.		
F.5 Yes = 1 No = 0 Has the state incorporated new regulations into the inspection form/checklist?		ſ
LR NOTES:		
·	- 0111	
WUTC has incorporated a large number of supplemental (State) regulations to the Federal Standard Inspection	a Checklist.	
F.6 Yes = 2 No = 0 Needs Improvement = 1 Did the inspector check to assure the operator is following its written procedures for (check all that	2	
apply):	<u> </u>	. *
a.,Abandonment	X	
b. Abnormal Operations	X	1.09
C.DICAR-OUT LAUAS		or of a
d. Compressor or Pump Stations	<u></u>	
eChange in Class Location	X	
***************************************	X	(Y_{i}, Y_{i}, Y_{i})
gCathodic Protection	X	
h. Cast IronReplacement		
i. Damage Prevention	X	
j. Deactivation	X	% II
k. Emergency Procedures	X	T-1,71,1
IInspection of Right-of-Way	X	
m. Line Markers	X	
n. Liaison with Public Officials	X	
oLeak Surveys	X	34
pMOP		
g.MAOP	$\overline{\mathbf{x}}$	$\sim \lambda^{-1}$

xPublic Education	X	
y. Purging	X	
z. Prevention of Accidental Ignitions	X	
A. Repairs	X	
B.Signs		•
C. Tapping	[X]	
D. Valve Maintenance	<u> </u>	
***************************************	<u> X</u>	
E. Vault Maintenance	<u>L</u>	
F. Welding	X	
SLR NOTES: Items not checked are not applicable to the operator's operation.	• .	
F.7 Yes = 2 No = 0 Needs Improvement = 1		
Did the hispector assure the operator's procedures are adequate for (check all that apply):	2	2
a. Abandonment	<u> X</u>	
b. Abnormal Operations	X	
c. Break-Out Tanks	🔲	
d. Compressor or Pump Stations		
eChange in Class Location	X	•
fCasings	X	
g. Cathodic Protection	X	
h. Cast IronReplacement	<u>[A]</u>	
iDamage Prevention	 [27]	
j. Deactivation	<u> </u>	
k. Emergency Procedures	<u>IX</u> I	
***************************************	<u> </u>	
1. Inspection of Right-of-Way	X	•
m. Line Markers	<u> </u>	
n. Liaison with Public Officials	X	
o. Leak Surveys	X	₹
p. MOP	П	
q.MAOP	X	,
r. Moving Pipe	 [V]	
s. New Construction] <u>자</u> *	5.7
tNavigable Waterway Crossings	<u> X </u>	÷
uOdorization		• :
{}^{}^{}^{}^{}^{}^{}^{}^{}^{}^{}^{}^{}^{	<u>X</u>	
v. Overpressure Safety Devices	<u> X</u>	14.43
w. Plastic Pipe Installation	П	
x. Public Education	X	in the second
y.Purging	X	
zPrevention of Accidental Ignitions	<u> </u>	
A. Repairs	X	
BSigns	<u> </u>	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
C. Tapping		
	<u> </u>	and the second of a second
B. Vault Maintenance B. Vault Maintenance	<u>X</u>	
FWelding	Ц	
	X	" 化成分物理
LR NOTES: Items not checked are not applicable to operations, and are not covered in the operator's O and M.		
TO Yes = 2 No = 0 Needs Improvement = 1 Consequent and the Salar Annual Consequent Salar Annual Consequent Salar S		
Did the inspector check to assure the operator? reports verify and and proceedings of the control of the contro	2	2
an mai appry.		
a. Abandonment	X	in the state of the state of the
b. Abriormal Operations	(X)	(1987年) 150日 (1967年) 1967 (1987年) 150日 (1967年)
C.DICAR-OUL TANKS	<u> </u>	to the problem of the
d. Compressor or Pump Stations	""百	ยที่เลิมเรียญให้สารณ์ได้เกียว เมล์เกรียนเลยติด (เกราะ 17 กับ
e. Change in Class Location	7	Salar page 18 (1887)
f. Casings	<u>101</u>	ownings (tod tree) it wile had owned to

	gCathodic Protection	X		
	hCast IronReplacement	$\overline{\sqcap}$		
	iDamage Prevention	$\overline{\mathbf{X}}$		
	jDeactivation	X		
	kEmergency Procedures			
	IInspection of Right-of-Way	.J <u>A</u> J		
		<u>앀</u>		
	m. Line Markers	<u>N</u>		
	n. Liaison with Public Officials	.国		
	o. Leak Surveys	.[조]		
	pMOP	Щ.		
	g.MAOP	X	•	
	rMoving Pipe	X		
	sNew Construction	X		
	tNavigable Waterway Crossings	\Box		
	u. Odorization	$\overline{\mathbf{x}}$		
	vOverpressure Safety Devices	লি		
	w. Plastic Pipe Installation	H		
•	xPublic Education			
7	***************************************	兽	* *	
	y.Purging	逆		
*	z. Prevention of Accidental Ignitions	X		
	A. Repairs	X	** ,	
	B. Signs	X		•
	C. Tapping	X		
	D. Valve Maintenance	X		
	E. Vault Maintenance	Ħ.	•	
•	F. Welding	Ϋ́		
		12.01		
SLR N	· · · · · · · · · · · · · · · · · · ·			
	Items not checked are not applicable to this operator.			
F. SLR N	the hispector have adequate knowledge of the pipeline safety program goals and regulations?	2		2
DERCIT	The inspector's demonstrated a superior knowledge of the pipeline safety program goals and regulations is superior.			
				· · · · · ·
F.1	What is the inspector observing in the field? Review the summary.	O		n
SLR NO		Ĭ. :		
	The inspector's areas of focus in the field were general, but comprehensive. He showed special interest in operator quali performance, regulator compliance, acceptable cathodic protection readings (especially at riser locations), valve condition pre-tested pipe was marked in compliance with Code requirements, atmospheric oxidation, and station security.	fication, ass	on (OQ) urance tha	at
F.1	1 Yes = 1 No = 0			1 1 2 2
1.1	Did the inspector conduct an exit interview?	i	•	1
SLR NO	OTES:			
	The exit interview emphasized O and M procedures that need to be revised or clarified, and records that were incomplete	or m	issing.	A. 35
F.1.		1		1
SLR NO				
		Idoror	it records	WAC
	The inspector identified the following probable procedure/record violations found during the inspection: Missing 2006 (480 - 93 - Use of calibrated equipment for leak surveys; Pipeline exposure reports; and, maintaining liaison with public of	officia	ls.	, 112.0
F.1.	The state of the s	0	1900 J.V	
SLR NO		2		
	The inspector was thorough in an examination of the operator's records to support it's pipeline safety program. During the inspector consistently compared documented records to the operator's O and M procedures as appropriate. The field audicomprehensive, focusing on regulator operations, cathodic protection, and Operator Qualification. Mr. Subsits is one of inquisitive field inspectors that I have ever observed. He methodically checks the operational details of facility operation individual field sites were inspected, including primary and satellite sites. These were evenly spread within and around twell as several remote sites. Special attention was given to cathodic protection and regulator set points versus actual operators included missing odorant records for 2006, use of calibrate equipment for leak surveys per requirements of Voipeline exposure reports, and inadequate procedures for liaison with public officials. In addition, the inspector held a firederal and State Code requirements, and showed courtesy in response to queries from the operator during the inspection	e insp t was in the monal sys he city rating VAC 4	ection, the methodical st thorous tems. End of Fernal pressure, 180-93, mowledge of	e al and gh and ght lale, as Areas issing
	Total points for this sec	cnou:		16 16

Rating

Washington

Program Type: 60105

PART		Possible Points	Points Scored
0	Representative Date and Title Information		
A	General Program Compliance	42	41
В	Inspections(Procedures, Records, forms)	36	34
С	LNG Inspections	11	11
D(1)	Compliance 60105(a) States	17	17
D(2)	Compliance 60106(a) States	••	- 7
D(3)	Compliance-Interstate Agents	20	20
Ε .	Incident Investigations	11	11
F	Field Inspection	16	16
TOTAI		153	150
State R	ating	· · · · · · · · · · · · · · · · · · ·	98

Program Evaluation SLR Comments

